ALFREDI, John 27 May 1976

Designation	Accident Location	Accident Due to
Per Way Inspector	Mt. Newman Railway	Track vehicle/Train Collision

John Alfredi died when his Hi-Rail vehicle ran into the rear of an empty ore train which was entering a siding on the Mount Newman Railway. **DMP Ref. FS-MG-768-415**

Source: *Department of Mines Annual Report 1976*